EXHIBIT 2



Return to Report

Order Information

Client

WARRANTY SERVICES

Claim ID

GSF64903-R

Order Date

8/30/2004 12:35:59 PM **RONALD BECKER**

Inspector Name Contract Number

PZH4599567

Insured Party Vehicle Year

NEWTON 1996

Vehicle Make

MOTOR HOME

Vehicle Model

ALLEGRO Vehicle VIN Number 4UZR69R14T2307472

Vehicle Mileage

29233

Facility Information

Facility Name

CUMMINS OF ALABAMA

Facility Address

2200 PINSON HWY

Facility City **Facility State** **BIRMINGHAM**

Facility Contact

AL DAVID **JDK**

Adjuster Adjuster

5852

Extension Adjuster Email

Reason For Inspection

VERIFY CYLINDERS FAILURE VERIFY WATER PIPE FAILURE-IS THIS CAUSE OF FAILURE OR RESULT OF FAILURE/OVERHEAT? VERIFY EXTENT OF ENGINE DAMAGE DAMAGE CAUSED BY OVERHEAT?

Report Information

Inspection Date

8/31/2004 3:30:00 PM

Vehicle Year

1996

Vehicle Make Vehicle Model

MOTOR HOME **ALLEGRO**

Current VIN Number

4UZR69R14T2307472

Current Mileage

29233

Vehicle Trim

Labor Rate / Type

95 PROVIDED VERBALLY

Engine Type

6B 5.9L INLINE 6 TURBO CHARGED **AUTO**

Wheel Drive Type

Transmission / Model

REAR WHEEL DRIVE (RWD)

Drained	Engine Oil Condition	Good
Drained	Coolant Condition	Good
Full	Transmission Condition	Good
Full	Power Steering Condition	Good
N/A	Brake Fluid Condition	N/A
N/A	Differential Fluid Condition	N/A
N/A	Transfer Case Condition	N/A
	Drained Full Full N/A N/A	Drained Coolant Condition Full Transmission Condition Full Power Steering Condition N/A Brake Fluid Condition N/A Differential Fluid Condition

Miscellaneous Comments

OIL FILTER ONVEHICLE IS FLEET GUARD.

Commercial Use ?	NO	Why	
Modifications ?	NO	What	
Collision ?	NO	Describe	
Tow Hitch ?	YES	Туре	TOW BAR FOR CAR
Towed or Driven In	DRIVEN		<i>5,</i>
Belts	GOOD		
Hoses	GOOD		
Overall Condition	GOOD		

Customer Complaint, Repair Order Number, Date Opened, Shop Name on Repair Order CHECK FOR KNOCKING.

State of Assembly (be specific)

THE ENGINE HAS BEEN REMOVED AND THE HEAD, PAN, AND THE #6 ROD AND PISTON HAVE BEEN REMOVED.

Any recalls TSB's, Oasis/Function 70, Parts Warranty?

NONE

Failed Components and Extent of Damage

THE #6 PISTON AND CYLINDER WALL ARE SCORED. NO DAMAGE TO ROD OR MAIN BEARINGS AND NO DAMAGE TO THE OTHER FIVE PISTONS OR CYLINDERS. THERE IS A HAIR LINE CRACK ON THE BOTTOM THREAD OF A 5/8" WATER PIPE SCREWED INTO THE THERMOSTAT HOUSING ON THE HEAD. NO SIGN OF EXTERNAL ENGINE OVERHEATING.

Measurements of Components

NONE

Cause of failure

EXACT CAUSE OF FAILURE IS UNKNOWN. BECAUSE OF THE HAIRLINE CRACK IN THE 5/8" WATER PIPE, ITS POSSIBLE THAT AN AIR LOCK FORMED AROUND THE #6 CYLINDER WATER JACKET. THE AIR LOCK MIGHT THEN HAVE CAUSED THE #6 CYLINDER TO OVERHEAT.


Recommendations for Repair

REPLACE THE ENGINE WITH A REMAN. NOTE THIS BLOCK CAN'T BE BORED AND IT CAN'T BE SLEEVED.

Inspector Signoff

View Images

Notes: VEHICLE Notes: VIN 4UZR69R14T2307472





Upload Date: 8/31/2004 10:16:56 PM

Notes: ODOMETER 29233




Upload Date: 8/31/2004 10:16:56 PM

Notes: SCORED #6 PISTON




Upload Date: 8/31/2004 10:16:56 PM

Notes: SCORED #6 CYLINDER WALL



Upload Date: 8/31/2004 10:16:56 PM

Notes: #5 CYLINDER AND PISTON



Upload Date: 8/31/2004 10:16:56 PM


Notes: PIPE ASSEMBLY

Upload Date: 8/31/2004 10:16:56 PM

Notes: HAIRLINE CRACK IS ON THE SECOND

THREAD FROM MY THUMB





Upload Date: 8/31/2004 10:16:56 PM

Notes: RUSTY AREA INSIDE PIPE WHERE THE CRACK IS LOCATED



Upload Date: 8/31/2004 10:16:56 PM

Notes: BROWN AREA IS WHERE PIPE SCREWED INTO THE HEAD; BROWN IS CORROSION FROM **LEAKAGE**

